

MIDIcontrol Power Supply from the OB-Xa

If you don't like to use an external power supply for your OB-Xa MIDIcontrol, then cut trace and solder a 10 OHM resistor as shown in the picture below.

